

# FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer)

(Re: G.O. Ms. 20/70/ PWD Dt. 23 - 01 - 1970)

Name of the School

: PES Vidyalaya

1. Name of the Officer
2. Location
3. Period for which the certificate is issued
4. Types of building
5. Nature of defect if any
  - a) Foundation and basement
  - b) Superstructure
  - c) Doors and windows
  - d) Wood work wrought and put up
  - e) Roof
  - f) Flooring
  - g) Miscellaneous (Cracks if any)
6. Any Major defects notices which will render the building unsafe in any manner
7. Whether maintenance works have been done properly
8. Whether the structure is sound or not for conducting classes

: Vathsala KV, Asst Engineer, LSO/D  
Kunhimangalam

: Madayi, Kammur

: 2023-24

: Permanent

: NIL

: NIL

: NIL

: NIL

: NIL

: NIL

: NIL

: NIL

: NIL

: NIL

: YES

: YES

: YES

: YES

1. A block  
GF - 1x64.25x6.60x3.30 (m)  
Verandah - 1x64.56x2.30x3.60  
FF - 1x64.25x6.60x3.30 (m)  
Verandah - 1x64.56x2.30x3.60  
2. B block  
GF - 1x61.30x6.90x3.50 (m)  
Verandah - 1x61.30x1.80x3.50 (m)  
FF - 1x61.30x6.90x3.50 (m)  
Verandah - 1x61.30x1.80x3.50 (m)  
3F - 1x61.30x6.90x3.50 (m)  
Verandah - 1x61.30x1.80x3.50 (m)  
N Block  
GF & FF - 1x22.10x4.07x3.30 (m)  
1x9.30x4.07x3.30 (m)

- Note:-
1. The stability of the structure should be examined also with reference to location altitude intensity of wind exposure or flood etc.
  2. Any additional observation if deemed necessary for the certificate may be furnished separately with the certificate.

## CERTIFICATE

Certified that the School was inspected by me on ..... 29-05-2023 .....  
and found to be fit / ~~unfit~~ to conduct classes for the period ..... 2023-24 .....  
for the reason stated above.

Place: ..... Kunhimangalam ..... (Seal)

Date: ..... 29-05-23 .....

Assistant Engineer  
**ASSISTANT ENGINEER**  
**L. B. G. D. SECTION**  
**KUNHIMANGALAM**